

## **Utility Conflict Report**

ER	Utility	CHARTER		Corridor	SW MILITA	.RY	SITE PHOTOS
OWNER	Contact	FRANK CY	PRIAN	ID	1082		
GENERAL INFO	Utility		COMMUNICATIONS				
	Size and Material		OVERHEAD TELECOMM LINES				pechun
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUT			JTE	
	Longitudinal or Crossing		LONGITUDINAL				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 1	63					
	Station 7	14+97.05					
	Offset 1	6.44					
	Latitude +	-29.356477					
	Longitude -	-98.50237					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	<b>Estimated Resolution Date</b>						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Related to utility ID 4191				
			No Charter fa	cilities on th	is pole		
	Date Collected		Date Modified			11/28/2018 6:59:12 AM	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800