

Utility Conflict Report

OWNER	Utility	ty CHARTER		Corridor	SW MILITA	ιRY	SITE PHOTOS		
	Contact	FRANK CY	PRIAN	ID	1126				
0									
GENERAL INFO	Utility		COMMUNICATIONS						
	Size and Material		OVERHEAD TELECOMM LINES				E		
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU			JTE			
	Longitudinal or Crossing		LONGITUDINAL						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 1	97							
	Station 8	863+30.32							
	Offset -	15.35							
	Latitude +	-29.356755					McDo		
	Longitude	-98.52796							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Related to utility ID 7093						
	Date Collected	Date Modified 12/18/2			018 4:05:25 PM				

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800