

Utility Conflict Report

OWNER	Utility	Jtility CHARTER		Corridor	SW MILITA	\RY	SITE PHOTO
N N	Contact FRANK CYI		PRIAN ID		1132		
0							110
GENERAL INFO	Utility		COMMUNICATIONS				
	Size and Material		OVERHEAD TELECOMM LINES				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUT			JTE	
	Longitudinal or Crossing		LONGITUDINAL				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 2	202					
	Station 9	901+91.16					
	Offset -	17.09					
	Latitude +29.356760						
	Longitude	-98.51588					TO PARING ONLY
SUE	Level of Investigation Req'd		NONE				S A STATE OF THE PARTY OF THE P
	Test Hole No		N/A				3- (44)
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		11/20/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Related to utility ID 7070 No Charter facilities on this pole				RANCE BURANZA 3-5700
Date Collected			Date Modified			11/28/2	018 6:59:12 AM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800