

## **Utility Conflict Report**

ER	Utility	CPS		Corridor	SW MILITA	.RY	SITE PHOTOS		
Z						u v i			
OWNER	Contact	BILL FEY		ID	1183				
INFO	Utility		GAS						
	Size and Material		UNKNOWN						
=									
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		LONGITUDINAL						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	142							
	Station 5	586+60.00							
	Offset 1	10							
	Latitude -	29.356584							
	Longitude	-98.54267							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
TION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		11/16/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Underground utility line						
LU			VIA improvements underway at this location, no longer included in MyLink Plans						
<u>S0</u>			location, no lo	nger moladi	oa iii iviyeiiik	i idilə	Early S		
RESOLI									
	Date Collected		Date Modified 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800