

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	RIGSBY		SITE PHOTOS		
OWNER	Contact	-		ID	302				
O	Contact	ANNTLON	_	טו	302				
GENERAL INFO	Utility		SANITARY SEWER			East End Glass			
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	95							
	Station 1	130+75.50					(COVALIUS)		
	Offset	9.09							
	Latitude -	+29.397940							
	Longitude	-98.43367							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A			4200.28443387 (8532330) 620(t) 168622307 (843922.AXI)			
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	<b>Estimated Resolution Date</b>								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			CAMINA			
	Comment		Manhole within sidewalk accessible route						
							48014145517 (3207453)		
	Date Collected		<b>Date Modified</b> 11/28/2018 6:59:12 AM						