

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITAF	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH	E	ID	3083				
0									
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING			C.			
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	120							
	Station 5	506+68.81							
	Offset 2	26.8822							
	Latitude -	+29.358969							
	Longitude	-98.56760							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A			1917			
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		8/14/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Back of curb to sewer manhole = 1'-11" Lid thickness = 1 3/4" Bottom of cone to surface = 2'-6"			,			
Date Collected 7/19/2018 8:13:55 AM Date Modified 11/28/2018 6:59:12 AM									

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800