

Utility Conflict Report

IER	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ	ID	3119	***	
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	134					
	Station	546+97.55				444	
	Offset	16.349				93	
	Latitude +29.357727						
	Longitude -98.55503						
SUE	Level of Investigation Req'd		NONE N/A N/A			INITS TO THE PARTY OF THE PARTY	
	Test Hole No						
	Test Hole Depth						
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Front of sidew Sidewalk widtl No pole ID CATV cable		cable box = 3'-9"		

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

11/28/2018 6:59:12 AM

Date Modified

7/24/2018 10:21:37 AM

Date Collected