

Utility Conflict Report

ER	Utility	CPS		Corridor	SW MILITA	RY	SITE PHOTOS		
OWNER	Contact	JAKE MAR	TINEZ	ID	3121				
GENERAL INFO	Utility		ELECTRIC						
	Size and Material		STANDARD POWER POLE, TIMBER						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE RO			DUTE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	135							
	Station 5	548+39.42							
	Offset 16.2565								
	Latitude -	ude +29.357702							
	Longitude	ngitude -98.55460							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Front of sidewalk to pole = 3'-8" Sidewalk width = 4'-0" No pole ID CATV cable Adjacent to existing VIA bus stop						
	Date Collected	018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800