

Utility Conflict Report

A A	Utility	AT&T		Corridor	SW MILITA	RY	SITE PHOTOS	
OWNER	Contact	PHILIP AUS	STINI	ID		MX I		
0	Contact	PHILIP AUX	DIIIN	טו	3122			
GENERAL INFO	Utility		COMMUNICATIONS					
	Size and Material		UNKNOWN					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			OUTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	135					FIXER UPPER # 87.9k (3)446-4991	
	Station 5	548+78.16						
	Offset	17.5007						
	Latitude -	+29.357665						
	Longitude	-98.55450						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Front of sidewalk to utility box = 2'-1" Sidewalk width = 4'-0" Unable to open lid Adjacent to existing VIA bus stop					
	Date Collected 7/24/2018 11:27:48 AM Date Modified 11/28/2						2018 6:59:12 AM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800