

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3146		
0	00	, <u></u>					
GENERAL INFO	Utility		SANITARY SEWER				
	Size and Material		STANDARD MANHOLE, CAST IRON				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	142					
	Station	583+13.69					
	Offset	17.5198					
	Latitude ·	+29.356716					
	Longitude	-98.54371					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	<b>Estimated Resolution Date</b>						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Bottom of manhole ring to surface = 1'-8.5" Lid thickness = 1 1/2" Manhole adjacent to front of sidewalk Sidewalk width = 4'-0"				
<b>Date Collected</b> 7/31/2018 10:24:45 AM <b>Date Modified</b> 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800