

Utility Conflict Report

IER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID	3182			
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD FIRE HYDRANT					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTI			ITE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station							
	Offset							
	Latitude +	atitude +29.530896						
	Longitude -98.64378							
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/28/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Hydrant adjacent to front of sidewalk Sidewalk width = 5'-0" Hydrant to gas valve = 1'-4 1/4" Hydrant to water valve = 1'-9"					
Date Collected 8/16/2018 8:47:05 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com