

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS
OWNER	Contact	ANN PECH	E	ID	3183		
0							
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD WATER VALVE, CAST IRON				RON
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUT				OUTE
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station						
	Offset	Offset					
	Latitude +	atitude +29.530979					200
	Longitude -	98.64378					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/28/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Top of valve to surface = 4'-9" Lid thickness = 1 1/2" Front of sidewalk to valve = 1'-2"				
	Date Collected8/16/2018 8:50 AMDate Modified11/28/						2018 6:59:12 AM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800