

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS
OWNER	Contact	ANN PECH	E	ID	3200		
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD FIRE HYDRANT			1/6	
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			OUTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW			TO SECOND	
LOCATION	Sheet No.						Bank
	Station						l l
	Offset						
	Latitude +29.509564						
	Longitude -98.63004						
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A			A Company Company	
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/28/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Edge of parking lot to hydrant = 2'-3" Hydrant to water valve = 10'-10"				
Date Collected 8/16/2018 4:05:16 PM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800