

## **Utility Conflict Report**

Ш	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID	3213			
<b>GENERAL INFO</b>	Utility		SANITARY SEWER					
	Size and Material		STANDARD MANHOLE, CAST IRON					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUT			UTE		
	Longitudinal or Crossing		CROSSING					
0	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station							
	Offset							
	Latitude +29.502259							
	Longitude -98.62561							
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/28/2018					
	<b>Resolution Status</b>		NO RESOLUTION WAS REQUIRED					
	Comment		Top of cone to surface = 1'-6" Power pole to manhole = 11'-8"					
	Date Collected 8/17/2018 1:19:18 PM Date Modified 11/28/						018 6:59:12 AM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com