

## Utility Conflict Report

<b>OWNER</b>	Utility	AT&T	Corridor	BANDERA	<b>SITE PHOTOS</b>
	Contact	PHILIP AUSTIN	ID	3235	
<b>GENERAL INFO</b>	Utility	COMMUNICATIONS			
	Size and Material	STANDARD MANHOLE, CAST IRON			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
<b>LOCATION</b>	Sheet No.				
	Station				
	Offset				
	Latitude	+29.493838			
	Longitude	-98.61720			
<b>SUE</b>	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
<b>RESOLUTION</b>	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	9/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Unable to open manhole Edge of drainage channel to manhole = 5'-5" Power pole to manhole = 7'-1"			
	Date Collected		8/20/2018 9:23:14 AM	Date Modified	

