

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3253			
INFO	Utility		WATER					
	Size and Material		STANDARD WATER VALVE, CAST IRON					
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
GEN	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station	Station					No. of the last of	
	Offset	Offset						
	Latitude +	titude +29.491468						
	Longitude -	ngitude -98.61276						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		9/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Back of sidewalk to valve = 1'-0 1/2" Sidewalk width = 5'-0" Top of valve to surface = 3'-8" Lid thickness = 1 1/2"					
Date Collected 8/20/2018 11:39:34 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800