

Utility Conflict Report

OWNER	Utility	TxDOT	Corridor	BANDERA	SITE PHOTOS		
	Contact	SUMAN SHRESTHA	ID	3256			
GENERAL INFO	Utility	STORM SEWER					
	Size and Material	STANDARD MANHOLE, CAST IRON					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station						
	Offset						
	Latitude	+29.491915					
	Longitude	-98.61364					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	9/13/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Bottom of cone to top of cone = 1'-10" Bottom of cone to surface = 2'-7" Driveway joint to manhole = 2"					
Date Collected		8/20/2018 11:56:51 AM		Date Modified		11/28/2018 6:59:12 AM	

