

Utility Conflict Report

IER	Utility	SAWS		Corridor	BANDERA	SITE PHOTOS		
OWNER	Contact	ANN PECHE		ID	4575			
GENERAL INFO	Utility		WATER					
	Size and Material		UNKNOWN					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		LONGITUDINAL					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 2	38]		
	Station 1	383+00						
	Offset 2	Offset 25						
	Latitude +29.496406							
	Longitude -98.61978							
	Level of Investigation Req'd		QLA					
SUE	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		ACCOMODATE - RELOCATION					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY					
	Comment		GIS indicates that a waterline could be located beneath proposed bus pad.					
			Request As-builts for line depth verification					
Date Collected 11/20/2018 10:10:50 AM Date Modified 12/19/2018 11:48:34 AM								

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com