

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA	SITE PHOTOS
OWNER	Contact	ANN PECH		4577		
0	7.1.1.1.20111					
GENERAL INFO	Utility		WATER			
	Size and Material		UNKNOWN			
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		LONGITUDINAL			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No. 2	272				
	Station 1	1473+85				
	Offset 2	25				
	Latitude +29.516964					
	Longitude	-98.63545				
SUE	Level of Investigation Req'd		QLA			
	Test Hole No		N/A			
	Test Hole Depth		N/A			
LUTION	Recommended Action		ACCOMODATE - RELOCATION			
	Estimated Resolution Date					
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			
	Comment		GIS indicates that a waterline could be			
			located beneath proposed bus pad. Request As-builts for line depth verification			
RESOLL						
R H						
	Date Collected 11/20/2018 10:22:31 AM Date Modified 12/19/2018 11:48:33 AM					

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800