

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS		
OWNER	Contact	ANN PECH	-	ID	4581				
0	Contact	ANNILON	_	iD .	4301				
GENERAL INFO	Utility		WATER			NGACTING INTERFERENCE AND A STATE OF THE STA			
	Size and Material		UNKNOWN						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		LONGITUDINAL						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 297								
	Station 1	1742+30							
	Offset -	23					THE CANADA		
	Latitude +	-29.488983							
	Longitude	-98.61034					片		
SUE	Level of Investigation Req'd		QLA						
	Test Hole No		N/A			Return Parket			
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		ACCOMODATE - RELOCATION						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY						
	Comment		GIS indicates located benea Request As-bi	th proposed		ion			
	Date Collected		Date Modified 12/19/2018 11:48:31 AM						