

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA	SITE	PHOTOS		
OWNER	Contact			ID	4584				
0	0001				1001				
GENERAL INFO	Utility		WATER						
	Size and Material		UNKNOWN						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			E A			
	Longitudinal or Crossing		LONGITUDINAL						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	336							
	Station	1890+40							
	Offset -	25							
	Latitude -	+29.520828							
	Longitude	-98.63816							
SUE	Level of Investigation Req'd		QLA						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		ACCOMODATE - RELOCATION						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			r			
	Comment		GIS indicates that a waterline could be located beneath proposed bus pad. Request As-builts for line depth verification			1			
	Date Collected		Date Modified 12/19/2018 11:48:29 AM						