

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	4586		
GENERAL INFO	Utility		SANITARY SEWER				
	Size and Material		UNKNOWN				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		LONGITUDINAL				
	Placement Relative to ROW		INSIDE ROW				
-OCATION	Sheet No. 3	41				1	
	Station 2	027+05					
	Offset -2	25				TTERNALS Seeke School Difference	
	Latitude +29.484896						
_	Longitude -	-98.59485					
SUE	Level of Investigation Req'd		QLA				
	Test Hole No		N/A				
<i>•</i> ,	Test Hole Depth		N/A				
	Recommended Action		ACCOMODATE - RELOCATION				
RESOLUTION	Estimated Resolution Date						
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY				
	Comment		GIS indicates that a water and/or sanitary sewer line could be located beneath proposed bus pad. Request As-builts for line depth verification				
Date CollectedDate Modified12/19/2018 11:48:28 AM							

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com