



## Utility Conflict Report

<b>OWNER</b>	Utility	CPS	Corridor	BANDERA	<b>SITE PHOTOS</b>
	Contact	JAKE MARTINEZ	ID	8001	
<b>GENERAL INFO</b>	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
<b>LOCATION</b>	Sheet No.				
	Station	N/A			
	Offset	N/A			
	Latitude				
	Longitude				
<b>SUE</b>	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
<b>RESOLUTION</b>	Recommended Action	ACCOMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Bandera corridor has not yet been surveyed This record is a placeholder and is not a confirmed utility conflict			
<b>Date Collected</b>		<b>Date Modified</b>		8/17/2018 3:17:37 PM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800