





Utility Conflict Report

OWNER	Utility		SAWS	Corridor	BANDERA	SITE PHOTOS	
	Contact		NINA BITTLE	ID	4585		
GENERAL INFO	Utility		WATER				
	Size and Material		UNKNOWN				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		LONGITUDINAL				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.		332				
	Station		2516+80				
	Offset		20				
	Latitude		+29.483072				
	Longitude		-98.59773				
SUE	Level of Investigation Req'd		QLA				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		ACCOMODATE - RELOCATION				
	Estimated Resolution Date						
	Resolution Status		UTILITY CONFLICT CREATED				
	Comment		GIS indicates that a waterline could be located beneath proposed bus pad. Request As-builts for line depth verification				
Date Collected						Date Modified	11/21/2018 2:51:37 PM