

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	BANDERA	SITE PHOTOS	
	Contact	NINA BITTLE	ID	4582		
GENERAL INFO	Utility	WATER				
	Size and Material	UNKNOWN				
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing	LONGITUDINAL				
	Placement Relative to ROW	INSIDE ROW				
LOCATION	Sheet No.	296				
	Station	1765+20				
	Offset	-25				
	Latitude	+29.492915				
	Longitude	-98.61588				
SUE	Level of Investigation Req'd	QLA				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION				
	Estimated Resolution Date					
	Resolution Status	UTILITY CONFLICT CREATED				
	Comment	GIS indicates that a waterline could be located beneath proposed bus pad. Request As-builts for line depth verification				
Date Collected		Date Modified		11/21/2018 2:51:37 PM		