


Data Collection Report

GENERAL INFO	LOCID	16	Latitude	+26.502848	
	Highway	US 83	Longitude	-99.071595	
	County	Starr	Element	Drainage	
	CSJ	0038-06-047			
	Map Link	https://maps.google.com/maps?t=h&q=+26.502848,-99.071595			
	Field Notes	Bridge-already been widened before			
SITE PHOTOS					
Photo 1					
Date Collected		11/13/2017 3:51:12 PM	Date Modified		
			11/13/2017 3:55:02 PM		

Data Collection Report

SITE PHOTOS



Photo 2



Photo 3

Date Collected 11/13/2017 3:51:12 PM

Date Modified 11/13/2017 3:55:02 PM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio | Austin | Houston | Fort Worth | Dallas
Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com

Data Collection Report

SITE PHOTOS



Photo 4



Photo 5

Date Collected 11/13/2017 3:51:12 PM

Date Modified 11/13/2017 3:55:02 PM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio | Austin | Houston | Fort Worth | Dallas
Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com