



Pavement Report

GENERAL INFO	<p>ID 269</p> <p>Corridor BS 123B</p> <p>Latitude +29.561853</p> <p>Longitude -97.967830</p> <p>Google Maps Hyperlink <a +29.561853,-97.967830"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.561853,-97.967830</p> <p>Field Notes Potential Repair</p>
UTILITY DETAILS	<p>Utility Pavement Repair</p> <p>Owner TXDOT</p> <p>Type Vertical</p>
SITE PHOTOS	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Photo 1</p>  </div> <div style="text-align: center;"> <p>Photo 2</p>  </div> <div style="text-align: center;"> <p>Photo 3</p> </div> </div>
<p>Date Collected 11/8/2017 12:29:34 PM Date Modified 12/11/2017 12:12:38</p>	