

Utility Conflict Report

JER.	Utility	CHARTER		Corridor	SW MILITARY	SITE PHOTOS		
OWNER	Contact	FRANK CY	PRIAN	ID	1074			
GENERAL INFO	Utility		COMMUNICATIONS					
	Size and Material		OVERHEAD TELECOMM LINES					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		LONGITUDINAL					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 161							
	Station 7	01+16.11				BY THE A		
	Offset 15.95 Latitude +29.356686							
						metro 7 3		
	Longitude -98.50682					+		
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Related to utili	ty ID 4184				

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

12/18/2018 4:04:52 PM

Date Modified

Date Collected