

Utility Conflict Report

OWNER	Utility	tility CHARTER		Corridor	SW MILITA	.RY	SITE PHOTOS		
	Contact	FRANK CY	PRIAN	ID	1110		OH!		
GENERAL INFO	Utility		COMMUNICATIONS				Car Service		
	Size and Material		OVERHEAD TELECOMM LINES						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE			
	Longitudinal or Crossing		LONGITUDINAL						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 1	79							
	Station 7	71+64.44							
	Offset -	16.74							
	Latitude +	29.358248					3 5 0 7		
	Longitude -	-98.55668					a Ö		
SUE	Level of Investigation Req'd		NONE				500 11 8		
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date						T		
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Related to utility ID 7132						
Date Collected				Date I	Modified	12/18/20	018 4:05:17 PM		