

## **Utility Conflict Report**

IER	Utility	CHARTER		Corridor	SW MILITA	ιRY	SITE PHOTOS		
OWNER	Contact	FRANK CY	PRIAN	ID	1122				
GENERAL INFO	Utility		COMMUNICATIONS						
	Size and Material		OVERHEAD TELECOMM LINES						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE			
	Longitudinal or Crossing		LONGITUDINAL						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 1	98							
	Station 8	344+78.09					240		
	Offset -	16.32							
	Latitude +	29.356819					2 1		
	Longitude -	-98.53384					5 b		
SUE	Level of Investigation Req'd		NONE				THE CONTRACT OF THE CONTRACT O		
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Related to utility ID 7106						
	Date Collected		Date I	Modified	12/18/2	018 4:05:18 PM			

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800