

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CHARTER	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	FRANK CYPRIAN	<b>ID</b>	1124	
<b>GENERAL INFO</b>	<b>Utility</b>	COMMUNICATIONS			
	<b>Size and Material</b>	OVERHEAD TELECOMM LINES			
	<b>Accessible Route</b>	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	LONGITUDINAL			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	195			
	<b>Station</b>	857+45.19			
	<b>Offset</b>	-16.47			
	<b>Latitude</b>	+29.356765			
	<b>Longitude</b>	-98.52987			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT			
	<b>Estimated Resolution Date</b>	10/26/2018			
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED			
	<b>Comment</b>	<p>Related to utility ID 7097</p> <p>Charter line does not extend to this pole</p>			
<b>Date Collected</b>		<b>Date Modified</b>		11/28/2018 6:59:12 AM	

