

Utility Conflict Report

IER	Utility	Itility CHARTER		Corridor	SW MILITARY	SITE PHOTOS
OWNER	Contact	FRANK CY	PRIAN	ID	1134	
0						A CARREST
GENERAL INFO	Utility		COMMUNICATIONS			
	Size and Material		OVERHEAD TELECOMM LINES			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		LONGITUDINAL			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No. 202					
	Station 9	01+93.75				
	Offset -15.9					
	Latitude +29.356853					
	Longitude -98.51588					
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			the section of the se
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		NO CONFLICT			085 GU
	Estimated Resolution Date		11/20/2018			Part of the state
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Related to utili No Charter fac	-	is pole	INSURANC ASEGURANA 1923-570

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

11/28/2018 6:59:12 AM

Date Modified

Date Collected