

Utility Conflict Report

_							
OWNER	Utility	AT&T		Corridor	SW MILITA	RY .	SITE PHOTOS
×	Contact			ID	1135		
0							
GENERAL INFO	Utility		COMMUNICATIONS				The state of the s
	Size and Material		OVERHEAD TELECOMM LINES				A STATE OF THE STA
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE		ITE		
	Longitudinal or Crossing		LONGITUDINAL				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	202					
	Station	903+34.80					
	Offset -	-16.69					
	Latitude -	+29.356806					2
	Longitude	-98.51552					496009
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				₩ 4468
	Test Hole Depth		N/A				6
RESOLUTION	Recommended A	action	NO CONFLIC	т			
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Related to utility ID 7067				
							20
Date Collected				Date I	Modified	12/18/20	018 4:05:29 PM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800