

Utility Conflict Report

OWNER	Utility	CHARTER		Corridor	SW MILITA	\RY	SITE PHOTOS		
	Contact	FRANK CY	PRIAN	ID					
0									
GENERAL INFO	Utility		COMMUNICATIONS						
	Size and Material		OVERHEAD TELECOMM LINES						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTI				JTE		
	Longitudinal or Crossing		LONGITUDINAL						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 2	208							
	Station 9	927+39.85							
	Offset -	22.37							
	Latitude -	29.356823					XOCEHO		
	Longitude	-98.50795							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Related to utility ID 7048						
	Date Collected	Date Modified 12/1			12/18/2	2018 4:05:38 PM			

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800