

## **Utility Conflict Report**

OWNER	Utility	CHARTER		Corridor	SW MILITARY	SITE PHOTOS		
	Contact FRANK CYF		PRIAN <b>ID</b>	1158				
0								
GENERAL INFO	Utility		COMMUNICATIONS					
	Size and Material		OVERHEAD TELECOMM LINES					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		LONGITUDINAL					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 2	211						
	Station 9	947+53.22						
	Offset -17.74 Latitude +29.356862							
								Longitude .
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	<b>Estimated Resolution Date</b>							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Related to utility ID 7036					

**Date Collected** 

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

12/18/2018 4:05:33 PM

**Date Modified**