

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	SW MILITA	ιRY	SITE PHOTOS		
OWNER	Contact	ANN PECH	E	ID	3113				
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	134					T		
	Station 5	546+36.97							
	Offset						Transfer of the second of the		
	Latitude -								
	Longitude	-98.55527							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	<b>Estimated Resolution Date</b>								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Top of valve to surface = 5" Lid thickness = 1 5/8" Front of sidewalk to valve = 2'-4" Sidewalk width = 4'-5"						
	Date Collected         7/24/2018 9:35:10 AM         Date Modified         11/28/						2018 6:59:12 AM		

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800