

## **Utility Conflict Report**

IER	Utility	CPS		Corridor	SW MILITA	RY	SITE PHOTO		
OWNER	Contact	ct JAKE MAR		TINEZ <b>ID</b>					
INFO	Utility		ELECTRIC						
	Size and Material		STANDARD POWER POLE, TIMBER						
GENERAL	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE						
GEN	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	173							
	Station 5	577+51.37							
	Offset 1	17.2206							
	Latitude -	+29.356863							
	Longitude	-98.54556							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	<b>Estimated Resolution Date</b>								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Pole ID: 473812 Conduit to front of sidewalk = 1'-3 1/2" Sidewalk width = 4'-0"						
	<b>Date Collected</b> 7/31/2018 10:00:20 AM <b>Date Modified</b> 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800