

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3157		
Ó							
GENERAL INFO	Utility		SANITARY SEWER				
	Size and Material		STANDARD MANHOLE, CAST IRON				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 1	45					
	Station 5	598+31.90					
	Offset 2	20.3827					
	Latitude +	-29.356542					
	Longitude -	-98.53896					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Sidewalk width = 5'-0" Manhole to front of sidewalk = 6'-1" Unable to open manhole				
Date Collected 7/31/2018 12:13:04 PM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800