

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>	
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	4186		
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC				
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER				
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE				
	<b>Longitudinal or Crossing</b>	CROSSING				
	<b>Placement Relative to ROW</b>	INSIDE ROW				
<b>LOCATION</b>	<b>Sheet No.</b>	196				
	<b>Station</b>	708+89.60				
	<b>Offset</b>	16.38				
	<b>Latitude</b>	+29.356585				
	<b>Longitude</b>	-98.50424				
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE				
	<b>Test Hole No</b>	N/A				
	<b>Test Hole Depth</b>	N/A				
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT				
	<b>Estimated Resolution Date</b>	9/17/2018				
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED				
	<b>Comment</b>	Pole ID: 380628 Pole to back of curb = 2'-11" Pole to back of sidewalk = 2'-1" Sidewalk width = 6'-1" Adjacent to existing VIA bus stop no. 56133 Relocate pole to ROW with electric lines cantilevered toward the roadway				
	<b>Date Collected</b>	8/6/2018 9:28:27 AM	<b>Date Modified</b>	11/28/2018 6:59:12 AM		

