

## **Utility Conflict Report**

**PHOTOS** 

	1					
VER	Utility	CPS		Corridor	SW MILITARY	SITE
OWNER	Contact JAKE MART		TINEZ	NEZ <b>ID</b>	4191	
GENERAL INFO	Utility		ELECTRIC			
	Size and Material		STANDARD POWER POLE, TIMBER			4
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.	162				
	Station	714+97.05				
	Offset	16.44				
		+29.356477				
		-98.50237				
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			717
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date					
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Pole ID: 38369 Pole to back of Pole to back of Sidewalk widtle Pole attached Relocate pole cantilevered to	of curb = 3'-9 of sidewalk = on = 6'-7" to adjacent to ROW wit	= 2'-1" pole. th electric lines	

**Date Collected** 

8/6/2018 10:30:11 AM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

12/18/2018 4:02:33 PM

**Date Modified**