

Utility Conflict Report

OWNER	Utility SAWS	Corridor US 90	SITE PHOTOS
	Contact NINA BITTLE	ID 201	
GENERAL INFO	Utility	WATER	
	Size and Material	STANDARD WATER VALVE, CAST IRON	
	Utility Conflict Description	WATER VALVE WITHIN PROPOSED SIDEWALK	
	Longitudinal or Crossing	CROSSING	
	Placement Relative to ROW	INSIDE	
LOCATION	Sheet No.	180	
	Station Origin		
	Start Station	652+67.07	
	Start Offset	12.87	End Offset
	Latitude	29.398920351	Longitude -98.644571185000004
SUE	Level of Investigation Req'd	NONE	
	Test Hole No	N/A	
	Test Hole Depth	N/A	
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE	
	Estimated Resolution Date		
	Resolution Status	UTILITY CONFLICT RESOLVED	
	Comment	ADJUST WATER VALVE LID TO PROPOSED GRADE DURING CONSTRUCTION (<1" VERTICAL CHANGE ANTICIPATED)	
Date Collected 9/20/2017 3:56:52 PM		Date Modified 8/17/2018 2:20:21 PM	

