

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	RIGSBY		SITE PHOTOS
OWNER	Contact	NINA BITTL	.E	ID	204		
Ó							
<b>GENERAL INFO</b>	Utility		WATER				
	Size and Material		STANDARD WATER METER, CAST IRON				
	Utility Conflict Description		WATER METER WITHIN PROPOSED SIDEWALK				
	Longitudinal or Crossing		CROSSING				
0	Placement Relative to ROW		INSIDE				
OCATION	Sheet No. 2	236					
	Station Origin						
	Start Station 1	04+12.97	End Station				
	Start Offset 1	0.98	End Offset				
	Latitude 2	9.397988856	Longitude	-98.4420211	36999998		
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
	Recommended Action		MINIMIZE - PROTECT IN PLACE				
	Estimated Resolution Date						
RESOLUTION	<b>Resolution Status</b>		UTILITY COORDINATION IN PROGRESS				
	Comment		ADJUST WATER METER LID TO PROPOSED GRADE DURING CONSTRUCTION (<1" VERTICAL CHANGE ANTICIPATED)				
	Date Collected	9/20/2017 4:	52:48 PM	Date M	odified	11/9/20	17 5:45:01 PM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com