

Utility Conflict Report

						ī
IER	Utility	SAWS		Corridor	RIGSBY	SITE PHOTOS
OWNER	Contact	NINA BITTL	.E	ID	212	
GENERAL INFO	Utility		WATER			HARTHING BLAX
	Size and Material		STANDARD WATER METER, CAST IRON			
	Utility Conflict Description		WATER METER WITHIN PROPOSED SIDEWALK			
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE			
LOCATION	Sheet No.	240				1
	Station Origin					
	Start Station	117+90.74	End Station			That is the state of the state
	Start Offset	12.41	End Offset			
		00 007000454				The state of the s
	Latitude	29.397968154	Longitude -	98.4376948	40000006	
<u> </u>	Latitude Level of Investi		NONE	98.4376948	40000006	
SUE				98.4376948	4000006	
SUE	Level of Investi	gation Req'd	NONE	98.4376948	4000006	THE STATE OF THE S
SUE	Level of Investig	gation Req'd	NONE N/A			
SUE	Level of Investignment of Test Hole No	gation Req'd	NONE N/A N/A			
	Level of Investignment Test Hole No Test Hole Depth Recommended	gation Req'd Action Date	NONE N/A N/A MINIMIZE - PR	OTECT IN F		
RESOLUTION SUE	Level of Investignment Test Hole No Test Hole Depth Recommended Estimated Reso	gation Req'd Action Date	NONE N/A N/A MINIMIZE - PR	OTECT IN F RDINATION ER METER I RADE DUR ON (<1" VEI	PLACE IN PROGRESS LID TO ING	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800