

Utility Conflict Report

ER	Utility	SAWS		Corridor	RIGSBY	SITE PHOTOS	
OWNER	Contact	NINA BITTL	F	ID	213		
0	Contact	111177 51112			210		
GENERAL INFO	Utility		WATER		HINGE HERE		
	Size and Material		STANDARD WATER METER, CAST IRON		With the state of		
	Utility Conflict Description		WATER METER WITHIN PROPOSED SIDEWALK				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE				
LOCATION	Sheet No. 240						
	Station Origin						
	Start Station	118+97.21	End Station			ALEXT MAN AND AND AND AND AND AND AND AND AND A	
	Start Offset	11.78	End Offset				
	Latitude	29.397968588	Longitude -98.437360506000005				
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A			THE PROPERTY OF THE PROPERTY O	
	Test Hole Depth		N/A				
	Recommended Action		MINIMIZE - PROTECT IN PLACE				
RESOLUTION	Estimated Resolution Date						
	Resolution Status		UTILITY COORDINATION IN PROGRESS				
	Comment		ADJUST WATER METER LID TO PROPOSED GRADE DURING CONSTRUCTION (<1" VERTICAL CHANGE ANTICIPATED)				
Date Collected 9/20/2017 5:37:15 PM Date Modified 11/9/2017 5:45:01 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800