



Utility Conflict Report

OWNER	Utility	SAWS	Corridor	RIGSBY	SITE PHOTOS	
	Contact	NINA BITTLE	ID	248		
GENERAL INFO	Utility	WATER				
	Size and Material	STANDARD WATER METER, CAST IRON				
	Utility Conflict Description	WATER METER WITHIN PROPOSED SIDEWALK				
	Longitudinal or Crossing	CROSSING				
	Placement Relative to ROW	INSIDE				
LOCATION	Sheet No.	235				
	Station Origin					
	Start Station	103+76.53	End Station			
	Start Offset	11.07	End Offset			
	Latitude	29.397989125	Longitude	-98.442135508		
SUE	Level of Investigation Req'd	NONE				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE				
	Estimated Resolution Date					
	Resolution Status	UTILITY COORDINATION IN PROGRESS				
	Comment	ADJUST WATER METER LID TO PROPOSED GRADE DURING CONSTRUCTION (<1" VERTICAL CHANGE ANTICIPATED)				
Date Collected		11/17/2017 1:06:10 PM	Date Modified		11/27/2017 10:43:29 AM	