



## Utility Inventory Report

<b>GENERAL INFO</b>	<p><b>ID</b> 165</p> <p><b>Corridor</b> BS 123B</p> <p><b>Latitude</b> +29.572517</p> <p><b>Longitude</b> -97.964734</p> <p><b>Google Maps Hyperlink</b> <a +29.572517,-97.964734"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.572517,-97.964734</a></p> <p><b>Field Notes</b></p>
<b>UTILITY DETAILS</b>	<p><b>Utility</b> Water Valve</p> <p><b>Owner</b> City of Seguin</p> <p><b>Type</b> Vertical</p>
<b>SITE PHOTOS</b>	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>Photo 1</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 2</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 3</b></p> </div> </div>
<p><b>Date Collected</b> 11/7/2017 12:13:26 PM      <b>Date Modified</b> 12/11/2017 12:12:38</p>	