



Utility Inventory Report

GENERAL INFO	<p>ID 166</p> <p>Corridor BS 123B</p> <p>Latitude +29.572569</p> <p>Longitude -97.964807</p> <p>Google Maps Hyperlink <a +29.572569,-97.964807"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.572569,-97.964807</p> <p>Field Notes 9" drop 5'x1.5' grate</p>
UTILITY DETAILS	<p>Utility Grate</p> <p>Owner TXDOT</p> <p>Type Horizontal and Vertical</p>
SITE PHOTOS	<div style="display: flex; justify-content: space-around; text-align: center;"> <div style="width: 30%;"> <p>Photo 1</p>  </div> <div style="width: 30%;"> <p>Photo 2</p>  </div> <div style="width: 30%; text-align: right;"> <p>Photo 3</p> </div> </div>
<p>Date Collected 11/7/2017 12:17:18 PM Date Modified 12/11/2017 12:12:38</p>	