



## Field Report

<b>GENERAL INFO</b>	<p><b>ID</b> 228</p> <p><b>Corridor</b> BS 123B</p> <p><b>Latitude</b> +29.581219</p> <p><b>Longitude</b> -97.964873</p> <p><b>Google Maps Hyperlink</b> <a +29.581219,-97.964873"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.581219,-97.964873</a></p> <p><b>Field Notes</b> Possible manhole</p>
<b>UTILITY DETAILS</b>	<p><b>Utility</b> Unknown</p> <p><b>Owner</b> Question</p> <p><b>Type</b> Horizontal and Vertical</p>
<b>SITE PHOTOS</b>	<div style="display: flex; justify-content: space-around; text-align: center;"> <div> <p><b>Photo 1</b></p>  </div> <div> <p><b>Photo 2</b></p>  </div> <div> <p><b>Photo 3</b></p> </div> </div>
<p><b>Date Collected</b> 11/7/2017 5:10:59 PM      <b>Date Modified</b> 12/11/2017 12:12:38</p>	