




## Sign Inventory Report

<b>GENERAL INFO</b>	<p><b>LOCID</b> 106</p> <p><b>Latitude</b> +29.566581</p> <p><b>Longitude</b> -97.96470</p> <p><b>Google Maps Hyperlink</b> <a +29.566581,-97.96470"="" href="https://maps.google.com/maps?t=h&amp;q=">https://maps.google.com/maps?t=h&amp;q="+29.566581,-97.96470</a></p> <p><b>Field Notes</b></p>
<b>SIGN DETAILS</b>	<p><b>MUTCD_Code</b></p> <p><b>Sign_Condition</b> Good</p> <p><b>Support_Condition</b> Good</p> <p><b>Anchor_Condition</b> Good</p> <p><b>Anchor_Type</b> Triangular Slip Base</p> <p><b>Direction</b> EB</p> <p><b>Retroreflectivity Check</b> YES</p>
<b>SITE PHOTOS</b>	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>Photo 1</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 2</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 3</b></p>  </div> </div>
<p><b>Date Collected</b> 1/8/2018 12:08:29 PM      <b>Date Modified</b> 1/23/2018 12:08:22 PM</p>	