




## Sign Inventory Report

|  |  |
|--|--|
| <b>GENERAL INFO</b>  | <p><b>LOCID</b> 43</p> <p><b>Latitude</b> +29.563947</p> <p><b>Longitude</b> -97.96448</p> <p><b>Google Maps Hyperlink</b> <a +29.563947,-97.96448"="" href="https://maps.google.com/maps?t=h&amp;q=">https://maps.google.com/maps?t=h&amp;q="+29.563947,-97.96448</a></p> <p><b>Field Notes</b></p>   |
| <b>SIGN DETAILS</b>  | <p><b>MUTCD_Code</b></p> <p><b>Sign_Condition</b> Good</p> <p><b>Support_Condition</b> Good</p> <p><b>Anchor_Condition</b> Good</p> <p><b>Anchor_Type</b> Triangular Slip Base</p> <p><b>Direction</b> EB</p> <p><b>Retroreflectivity Check</b> YES</p>  |
| <b>SITE PHOTOS</b>   | <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>Photo 1</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 2</b></p>  </div> <div style="text-align: center;"> <p><b>Photo 3</b></p>  </div> </div> |
| <p><b>Date Collected</b> 1/5/2018 1:12:53 PM      <b>Date Modified</b> 1/23/2018 12:08:22 PM</p> |  |